

## Software Update Notification

You will need a Windows-compatible computer and a (pin to pin) RS-232 cable.

RECOMMEND UPDATING ALL UNITS.

UPDATE UNITS S/N: \_\_\_\_\_  
PLEASE ADVISE CUSTOMERS AND UPDATE UNITS ONLY WHERE APPLICABLE.

NEW FEATURES ADDED IN THIS SOFTWARE RELEASE ARE INTENDED TO IMPROVE OPERATION/PERFORMANCE. UPDATE IS OPTIONAL.

Dependencies and requirements for this software update (this info is accessible through pressing: MENU-STATUS->VERSION INFO):

---

---

---

---

---

Release Notes: The software update will provide functionality/ usability improvements to the features and capabilities of this model. These are as follows:

- Addresses issue that can cause unit to fail to recognize first disc loaded out of standby
- Increases start up speed
- Increases HDMI Video quality

### IMPORTANT INFORMATION READ BEFORE UPDATING

- This codes contains 3 identified issues:
- On CD audio playback the disc timing on the touchscreen display can intermittently lose sync. Audio quality and sonic performance is not affected
- Track programming remains non-functional
- MP3 playback can experience intermittent drop outs

**DO NOT UPDATE YOUR UNIT IF ANY THESE PERFORMANCES ARE UNACCEPTABLE**  
**CLASSE INTENDS TO ADDRESS THESE ISSUES IN A FUTURE SOFTWARE RELEASE**